

Feb 2, 2016 11-7 Shift Notes

BASF EMPLOYEES

65 Last Recordable
133 Last Lost time

SAFETY Notes: Check the walkways for ice and treat with icemelt. Need to remind operators that Styrene material on line #2 can't be washed down the drain. Building 31 sump currently shut off.

Title V Notes: Trimer – Running in ORP mode.

CTO - Repairs complete, will be tested on dayshift Monday.

<u>F-1 Scrubber</u> – Continue sampling of scrubber and sump in building 31.

<u>Powder Room DC</u> – found with blowdowns off. Continuing blowing down. Replace the bags as soon as we can.

#1 MED / D 1780:

End seals are still being repaired. Start up when they are finished.

When we start do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed.

#1 RC / D 1780:

Currently out of feed. Continue feeding as feed is available

#2 MED line / Styrene:

Dryer Drive belt has been repaired. The oscillator belt needs to be repaired further WOW for page to rebuild. Will need the dryer cleaned up for Page needs to make a repair to oscillator belt.

There are drums of wet mix. There are also several drums of material that will need to be refed through the dryer. The auger was changed on second shift Sunday to auger 13 after 87 batches.

Will be down for most of the weeks due to refires.

Need to remind operators that Styrene material can't be washed down the drain. The new mixer plows should be in the week of the 2/29.

#2 RC/ Styrene:

Refiring all of lots 4 and 5. Continue.

Continue keep an eye on the liners in the bags; have had few instances where it falls in. The Floor CRT will need to take a sample out of the F1 scrubber and the sump in building 31 to wastewater. Before unlocking building 31 sump WWTP

CONFIDENTIAL BASF_114_022034

will test these samples for moly and if the sump is low, we can unlock and send to WWTP. At all other times the west sump will remain locked out.

Need to remind operators that Styrene material can't be washed down the drain. The new mixer plows should be in the week of the 2/29.

#3 MED line / AL 3945:

Started back up on afternoons. Continue to run

Talk to your relief on proper extruder settings to run this product.

Please keep a close eye on the ammonia and nitric additions.

#3 RC / AL-3945:

Continue feeding.

2 bags of old material have been fed to the calciner.

#4 RC / D-0222 Cleaning:

Had to scavenge off the syntron sock for #1. Hopper is currently taped off.

#5 RC / Catoxid:

Continue feeding. Missed samples are in the lab

2 bags of wet material to wait for engineering - don't feed now.

Do not overfill the hopper!

Continue to monitor 5A after filter. The log sheet is in the 2nd floor MCC room bldg. 11 - needs to be filled out every 2 hrs.

#6 RC & Dryer / D-0761:

Continue feeding. Missed sample is in the lab. Should have all buggies full. Watch for any brown material coming off the calciner. There is a check weigh scale located in the middle of building 27. Please check weigh all drums. 2 drums of overweight material have been consumed back into the run. As we get full drums by the check weigh station we need to put them back into production.

West Pfaudler / D- 0222 NEXT:

Solution tank has been prepared and was adjusted on afternoon shift. New sample is in the lab.

Lid was put back on. TDR in for Al 3945. Still waiting for it to be moved into pass. Hold for engineering before starting batch.

East Pfaudler/ D-0761:

Pfaudler and hopper should be empty by the end of afternoon shift. need to make a batch on midnights.

We did not run on afternoons due to manpower and having enough material. We need to be sure not to get too far ahead because the material quickly dries out and sticks in the buggies.

CONFIDENTIAL BASF_114_022035

Using the D0713 Lot #462 and 463 that has been released. See MOD for article # explanation.

6 Tank: Tank empty

Valve fixed. There was a screen and band clamp in the valve.

7 Tank: D-0222 Solution

Made adjustment on afternoon shift. New sample is in the lab.

National Dryer / D-5206:

Need to get national closed up and lit.

PK Blender / Catoxid:

We started making Catoxid on afternoons. Continue as able.

Need to make sure that the building is being cleaned up!

Make sure the dust collector and scrubber are within range before starting.

Watch level of Cr tank as indicator is still not working.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down.

We need to install another row of bags in the DC when able.

DC gauge has been added to the Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25.

Abbe Blender / D 5206:

HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

Tower 3 / Cu-0860:

Tower started the Cu 0860 reduction.

Tower 6 / Cu-0860

Towers loaded. Hold for engineering. There is exposed wire in the tower need to get this fixed before starting up.

Repacking in screening room:

North Screener /Cu-1155:

Screener is set up for Cu-1155.

South Screener /Cu 0860:

South Screener is set up for 0860.

#2662 (west) Pill Machine /

CONFIDENTIAL BASE 114 022036

Back together and holding.

#2664 (east) Pill Machine /

Back together and holding.

TK #2 / Zr-0404:

Continue loading and unloading.

TK #4 / Cu 0203:

We are done.

FYI – this product contains chrome and TK area is now a regulated area. Please wear your respirators in this area.

Milling V 2046: N/A

Harrop Kiln / Al 3920:

Kiln is lit and coming up to temp but stalled out about 100 deg from set point. WOW for issue.

Saggers have been switched out and are ready for next run.

Building 27 Belt Filter / Cu-6081:

Need to clean out the dryer chamber for Page to do some work. Holding for more material/Start up orders/ We have switched to 188 lined super sacks. These will need cardboard sleeves around them.

These are our five highest priorities

SLY repair

CTO repair

1 Line startup – some programming issues in power room

Line 2 Spiral for styrene

KLP startup – finish Pfaudler setup so we can start

Maintenance notes: New mixer plows for #2 mixer are due in the week of 2/29.

CONFIDENTIAL BASF_114_022037